

# Service Bulletin

TO: All Concerned, Rail

SUBJECT: Track Out of Service, Ravenswood Route

EFFECTIVE: Monday, April 1, 1991 - 1000 hours to  
Monday, May 20, 1991 - 1500 hours

As shown above, the Side Track at Kimball Terminal between interlocking Switch 5 and the bumping post will be out of service. A contractor will be renewing the Side Track platform.


## SPECIAL NOTICE

- Motormen must operate with extreme caution in the area and be prepared to honor any signal.
- 600 Volt traction power will be removed on the out of service track.
- It will not be possible to make the following train movements:

From signal 6R to 14L.  
From signal 10R to 14L.  
From signal 14R to 14L.


Please contact your superintendent if you have any questions.

Charge to J.O. 7904.

  
Director, Rail Service

  
Acting Manager, Rail Service

Approved:

  
Senior Manager,  
Transportation Service

RAJ:AJ:jc (JB5: S92-91)  
3/25/91