


Service Bulletin

TO: All Concerned, Rail
SUBJECT: Signals Removed from Service, North-South Route
EFFECTIVE: Sunday, May 19, 1991 - 1200 hours



As shown above, Signal R10, L18, R22, R26, Howard North Interlocking will be removed from service.

Please contact your superintendent if you have any questions charge to J. O. 7079.

J. Schenck 897

Director, Rail Service

W. Nichols

Manager, Rail Service

Approved:

W. Lavelle

Senior Manager,
Transportation Service