

RAIL
file x
post x
spl x
S366-91

Service Bulletin

TO: All Concerned, Rail

SUBJECT: Track Out of Service, Howard Terminal,
North-South Route

EFFECTIVE: Monday, July 15, 1991 - 1000 hours to
Monday, August 12, 1991 - 0400 hours

As part of the Howard Yard Renewal Project, southbound track 1 between double-slip switch number five (5) and the north end of the southbound platform will be out of service. A bumping post will be installed on track 1 at the north end of the southbound platform. The only access into track 1 pocket will be through Howard South Interlocking.

SPECIAL NOTICE

- All train movements into track 1 pocket must be authorized by the terminal supervisor.
- All personnel must operate with extreme caution past the work area and be prepared to honor any signal.

Please contact your superintendent if you have any questions.

CHARGE

J.O. 0805.

L. Schwerb 287
Director, Rail Service

W. Nichols (21)
Manager, Rail Service

Approved:

[Signature]
Senior Manager,
Transportation Service

WJN:AJ/jc (JB9:S366-91)
7/1/91

