

RAIL
file x
post x
spl x
S716-91

Service Bulletin

TO: All Concerned, Rail

SUBJECT: Reroute of Trains, North-South Route

EFFECTIVE: Friday, November 15, 1991 - 2200 hours to
Monday, November 18, 1991 - 0400 hours

As part of the Howard Track Renewal Project, a contractor will be installing a new switch on Track 4, near the yard leads. While this work is being done, a portion of track 4 will be out of service. All northbound North-South trains entering Howard Terminal will be rerouted into pocket 1 or pocket 2. CTA construction inspector, radio call number, K856, channel 2, will be in charge of the work site.


Howard towermen will be responsible for maintaining service while this reroute is in effect.

Please contact your superintendent if you have any questions.

CHARGE

Supervision - J.O. 0805

Trainmen - Deviation Code 03.
J.O. 0805



J. Schenck
Director, Rail Service

W. Nicholas (25)
Manager, Rail Service

Approved:

M. L. Wells
Senior Manager,
Transportation Service

WJN:LS:JP/jc (T1:S716-91)
11/12/91