


Service Bulletin

TO: All Concerned, Rail

SUBJECT: Signal Removed From Service,
Howard North Interlocking

EFFECTIVE: Saturday, April 4, 1992 - 1000 hours

Signal L26, Howard North Interlocking, will be permanently removed from service.



CHARGES

Instruction - J.O. 0805.

Supervision - J.O. 0805.

Trainmen - Deviation Code 03.
J.O. 0805.

J. Schenck
Director, Rail Service

William J. ...
Manager, Rail Service

LS:jc (J10:S118-92)
3/31/92