

Service Bulletin

TO: All Concerned, Rail
FROM: Track Temporarily Out of Service, Reroute, West-South Route
EFFECTIVE: Monday, March 18, 1991 - 0001 hours until further notice

As shown above, the **Southbound Track** between Roosevelt Road and 15th Street will be out of service until further notice. Trains will be rerouted through the area over a newly constructed Center Track.

ROUTING

Southbound Trains will enter the Center Track at Roosevelt Road and return to the **Southbound Track** through a turnout at 15th Street and then proceed normal.

SPECIAL NOTICE

- The Center Track will be fed from power section 101 at the north end and 103 at the south end.
- Cab signal equipment has been relocated to the Center Track.

ATTENTION MOTORMEN

The following rules apply:

- R8.2 Operation on sight
- R8.10 Safe operation of trains

Please review these rules and contact your superintendent if you have any questions.

Charge to J. O. 7134.

[Signature]
Director, Rail Service

[Signature]
Acting Manager, Rail Service

Approved:
[Signature]
Senior Manager,
Transportation Service

RAJ:AJ:jc (JB5:S82-91)
3/11/91

