

Chicago Transit Authority
Operations Division


Read

RAIL
file x
post x
spl x
S329-91

Service Bulletin

TO: All Concerned, Rail
SUBJECT: Signal and Crossover Removed from Service,
Howard South Interlocking, North-South Route
EFFECTIVE: Tuesday, June 25, 1991 - 2100 hours

Signal L28 and Switch 37 at Howard South Interlocking will be permanently removed from service.



PERMANENTLY REMOVED FROM SERVICE

No Short X-OVER - IT'S GONE

Please contact your superintendent if you have any questions.

Charge J. O. 7079.

[Signature]
Director, Rail Service

[Signature]
Manager, Rail Service

Approved:

[Signature]
Senior Manager,
Transportation Service

WJN:JP/jc (JB9:S329-91)
6/17/91