

# Service Bulletin

RAIL  
file x  
post x  
spl x  
S613-91

TO: All Concerned, Rail  
SUBJECT: Track Out of Service, North-South Route, Howard Terminal  
EFFECTIVE: Monday, September 30, 1991 - 0600 hours until further notice

As shown above a portion of track #2 within the Howard North Interlocking limits will be removed from service between signal L3 and switch 25-29. At the same time switches 1 and 5, and signals L3 and R2A will be permanently removed from service.

## SPECIAL ROUTING

A bumping post will be installed at the north end of pocket #2.

