

# Service Bulletin

TO: All Concerned, Rail  
SUBJECT: Reroute of Trains, North-South Route  
EFFECTIVE: Friday, November 22, 1991 - 2200 hours to  
Monday, November 25, 1991 - 0400 hours

A contractor will be making the final track and signal connections before returning the north end of track 3 to service. At the same time, the northbound Evanston track will be realigned. When finished, the temporary Evanston track connection from track 4 will be removed. While this work is being done, a portion of track 4 will be out of service. All northbound North-South trains entering Howard Terminal will be rerouted into pocket 1 or pocket 2. CTA construction inspector, radio call number, K856, channel 2, will be in charge of the work site.

Howard towermen will be responsible for maintaining service while this reroute is in effect.

Please contact your superintendent if you have any questions.

**CHARGE**

Supervision - J.O. 0805  
Trainmen - Deviation Code 03.  
J.O. 0805

*[Signature]*  
Director, Rail Service

*[Signature]*  
Manager, Rail Service

Approved:

*[Signature]*  
Senior Manager,  
Transportation Service

WJN:LS:JP/kc (T1:S711-91)  
11/6/91

