

RAIL
file x
post x
spl x
S736-91

Service Bulletin


TO: All Concerned, Rail

SUBJECT: Track Returned to Service, Howard Terminal,
North-South Route

EFFECTIVE: Monday, November 25, 1991 - 0400 hours

The north end portion of Track 3 at Howard Terminal will return to service. The bumping post located at the north end of Track 3 Pocket has been removed. Track 3 Pocket has been reconnected with Howard North Interlocking.


Director, Rail Service


Manager, Rail Service

Approved:


Senior Manager,
Transportation Service

WJN:LS/jc (JB13:S736-91)
11/21/91