

BUS  
file x  
post x  
spl x  
S745-91

# Service Bulletin

TO: All Concerned, Rail  
SUBJECT: Tracks out of Service, Howard, North-South Route  
EFFECTIVE: Monday, December 2, 1991 - 0900 Hours

The following yard tracks at Howard Yard, North-South Route will permanently be removed from service.

The associated switches on the south lead for these tracks will be spiked and clamped in the normal position.

- |               |               |               |
|---------------|---------------|---------------|
| Track 1 South | Track 3 South | Track 5 South |
| Track 2 South | Track 4 South | Track 6 South |

### CHARGES

Supervision - J.O. 0808  
Trainmen - Deviation Code 02  
J.O. 0808

*L. Schenck*  
Director, Rail Service

*W. D. Spinks*  
Manager, Rail Service

Approved:

*M. Saville*  
Senior Manager  
Transportation Service

WJN:LS:JP/tjc (T2:S745-91)  
11/27/91

