

Service Bulletin

RAIL
file x
post x
spl x
S41-92

TO: All Concerned, Rail

SUBJECT: Track Removal from Service, Howard Yard, North-South Route

EFFECTIVE: Friday, January 24, 1992 - 2200 hours


As part of the Howard Yard Track Renewal Project, the south lead, Howard yard will be permanently removed from service. At the same time interlocking switch #19 and signal R16 will also be permanently removed from service.


Please contact your superintendent if you have any questions.

CHARGE

Supervision - J.O. 0808.

Trainmen - Deviation Code 03.
J.O. 0808.


Director, Rail Service


Manager, Rail Service

LS:EBC/jc:lam (J9:S41-92)
1/23/92