

Service Bulletin

RAIL
file x
post x
spl x
S65-92

TO: All Concerned, Rail


SUBJECT: Track Out of Service, North-South Route

EFFECTIVE: Tuesday, February 25, 1992 - 0500 hours until further notice

As part of the Howard Track Renewal Project, **Track 4 will be out of service from switch 43B to double slip switch 0-23.** This will permit construction of the new Howard Yard configuration. All northbound trains will be routed from pocket 4 through #43 switch to track 3 and then through #37A - 39 switches into Howard Yard.

Howard towermen will be responsible for maintaining service while this reroute is in effect.

Please contact your superintendent if you have any questions.



CHARGE:

Supervision - J.O. 0805

Trainmen - Deviation Code 03.
J.O. 0805

E. B. Colwell III
Superintendent III,
North Rail District

L. Schenck
Director,
Rail Service

DFC:lam (L4:S65-92)
2/18/92