## STANDARD OPERATING PROCEDURES

## REPORTING TROUBLE

Shown on this card is the procedure to be followed by all employes when reporting trouble to the Radio-Telephone Operator.

IBT telephone - MOhawk 4-7200 - ask for Radio-Telephone Operator.

CTA telephone - Dial 2345.

The Radio-Telephone Operator must be notified under any of the following circumstances:

- Defective vehicle or equipment (for Bus Operators, as indicated in "Employes" Guide To Equipment Trouble.")
- Blockades, delays, or interruptions of service.
- 3. Unsafe conditions involving roadway or overhead wires.
- 4. Involvement in traffic accidents.
- 5. Collision with other CTA vehicles.
- 6. All accidents in which a person is injured.
- CTA vehicle or train strikes a pedestrian, even if pedestrian claims no injury.
- 8. Incidents involving arrests.
- 9. Relief does not show up.
- 10. Robberies.
- 11. Fire on CTA vehicle, train, or CTA property.
- 12. Any circumstance in which you are in doubt as to the proper procedure to take.



The following information must be given to the Radio-Telephone Operator, preferably in the order listed:

1. Badge number, or Agent's tag number.

- Location of occurrence (on Surface, give house number or intersection; on Rapid Transit, give nearest station).
- 3. Nature of occurrence.
- 4. Run number and route.
- 5. Direction.
- 6. CTA vehicle number.
- 7. Time of occurrence.
- 8. Length of delay.

Tell exactly what happened and be sure to report the following facts:

- 1. Condition of CTA vehicle or CTA property.
- 2. Number of passengers in CTA vehicle.
- 3. Number of passengers in other vehicle.
- 4. Injuries, if any.
- 5. Number of witnesses.

If any further information is required, the Radio-Telephone Operator will so instruct the employe.