

Rail	file	X	BUS	file	
	post	X		post	
	spl.	X		other	
				S303-78	

# Service bulletin

FRED - CHECK THIS  
OUT

TO: All Concerned, Rail

SUBJECT: Change in Train Berthing, Granville Station, North-South Route

EFFECTIVE: Monday, August 21, 1978 - 1000 Hours

On the above date and time, the motormen's berthing markers and conductor's safety stripes will be relocated north of present locations at Granville Station, North-South Route.

Please contact you Superintendent if you have any questions.

8-21-78

BERTHING MARKERS AND CONDUCTOR'S SAFETY STRIPES HAVE BEEN RELOCATED

R. Pythariz

\*

SIGNAL XYL LOCATED BETWEEN TRACKS 1+2 IS 12' NORTH OF THE NORTH END OF THE OLD PLATFORM THIS SIGNAL HAS A SIGN STATING FOR TRACK #2. THE NEXT SIGNAL IS 75' NORTH OF SIGNAL XYL AND STATES FOR TRACK 1

M. LaVelle  
Director, Services

R. Pythariz  
Manager, Transportation

8/14/78

RECEIVED  
C.T.A.

AUG 17 1978

SAFETY DEPARTMENT  
SAFETY PERFORMANCE ANALYSIS